

3039 BENZ Fan Belt Service Wrench (3 hole)



- Special designed with 3 holes to hold the stud on fan clutch assembly found on Mercedes Benz vehicle to allow release of lock nut.
- Slim handle for tight space operation.