

# 9023 C.V Joint Banding Tool (with cutter)



- Easily remove by sliding sideways after winding has been complete.
- Instruction:
  - Place band around boot and through nose of tool and through slot in winding body.
  - Using a 1/2" socket wrench or by hand wind the band until sufficient is applied.
  - Rotate handle over the boot to lock the band.
  - Slide tool free-end down with a hammer.
- Made In Taiwan