

3006 Power Bar Impact Wrench (1/2" Dr)



- Special designed to replace the harmonic balancer pulley which will turn when you try to remove the center nut.
- Up to 600ft/lb of torque.
- Applicable: pulley, flywheel, couplings and flangers etc.
- Made In Taiwan