3166 Non Contact IR Thermometer with laser Point



- Range : -30°C ~ 550°C
- Accuracy:
 - $^{\circ}$ ±2°C on -30°C to 100°C
 - $_{\circ}$ ±2°C on 101°C to 550°C
- Fixed emissivity (ϵ) 0.95
- Field of view: 100mmØ at 1000mm
- Use with 9V battery (Included)
- Auto off power feature.
- Comes with pouch bag.
- Made In Taiwan